




S/N 09/849,061
Filed 5/4/2001
Replacement Sheet

1 / 15





S/N 09/849,061
Filed 5/4/2001
Replacement Sheet

2/15




FIG.2A




FIG.2B



S/N 09/849,061
Filed 5/4/2001
Replacement Sheet

3/15




FIG.2C

4/15

	A	B	C	D
1				
2				
3				
4				■

FIG.3




FIG.4

5/15




FIG.5A




FIG.5B

6/15




FIG.5C




FIG.5D

7/15




FIG. 6

8/15




FIG.7

9/15

EQUIPMENT BROADCASTERS




FIG.8

10/15




FIG.9



S/N 09/849,061
Filed 5/4/2001
Replacement Sheet

11/15




FIG. 10



12/15




FIG.11



13/15

	A	B	C	D	E	F	G	H
1								
2	[0] ->	[0]=WORKBOOK NAME						
3	[1]	->	[0]	->	[0]=WORKSHEET1 NAME			
4			[1]	->	[0] -> [0]=TYPE[0]	[1] -> [0]=TYPE[1]		
5					[1] -> [0]=DESCRIPTION[0]	[1] -> [0]=DESCRIPTION[1]		
6					[2] -> [0]=DATA[0]	[1] -> [0]=DATA[1]		
7								
8								
9								
10								
11								
12					[1] -> [0]=WORKSHEET2 NAME			
13					[1]	->		
14								
15								
16								
17								
18								
19								
20								
21					[2] -> [0]=WORKSHEET3 NAME			
22					[1]	->		
23								
24								

FIG.12



S/N 09/849,061
Filed 5/4/2001
Replacement Sheet

14/15

901, Global Operation Functions

Search database | Program Setup | Vinestone Home |

VS-WorkWeb

search projects

View by Review Group

905, View Tree

- Executive Program Committee
 - Factory Executive Team
 - +Electrical Systems Coordination Team
 - +Water Systems Coordination Team
 - +Facilities Management Team
 - +Safety Coordination Team
 - +Factory Layout Coordination Team
 - Process Executive Team
 - Front End Process Review Team
 - +Isolation Team
 - Transistor Team
 - 06022000-122 Increase Beam Current in Tip Implant
 - 06082000-127 Change Impeller H₂SO₄ pump to Teflon
 - 05242000-127 Retarget Oxide Thickness in Furnace
 - +Bipolar Team
 - Back End Process Review Team
 - +Interconnect Team
 - +Interlayer Isolation Team

New

FIG.13A

FIG.13A

FIG.13

FIG.13A



15/15

902, Application Tabs

Specifications	Check Lists	Yield Data	Project Set Up
Summary	Experiment	SPC	Electrical

Change Impeller H₂SO₄ pump to Teflon

Current Status:

Approved by Factory Executive Team
Pre-implementation
3 pending action items
2 unread emails (J.Hyde, D.Zook)

Originator

Jack Hyde ▾

Functional Group

Wet Chemistry ▾

Origination Date: 05-JUNE-2000

Sponsors:

Add to List ▾

View List ▾

Coauthors:

Project Attributes:

Content Area, 904

Based on Project

H202 Filter Recycling ▾

WorkFlow Type

Equipment Mod ▾

Impact Level

Global High Risk ▾

Sharing

View External List ▾

Public ▾

Long Text Description:

Nylon Impeller has been observed to disintegrate in strong H₂SO₄ solution, shedding particles on wafers exposed to resist strip. The proposed change is intended to solve this problem. Impacts all Type 6 wet clean station in all factories running the S3003 process.

Meet Online Email Forum Whiteboard Meeting Minutes Schedule Action Item

903, Communication Tools

FIG.13B